

- ★ Chartered Engineer ---- 147273-3
- ★ Constructions & Consulting Civil Engineer
- ★ Govt. Approved Coimbatore District Collector's Soil Stability Panel Engineer R.Dis : 7194 / 2017 / C2 - CLASS - 1A
- ★ Licensed Bldg. Surveyor for Coimbatore Corporation Reg. No. 246 / 2009 / Grade I.
- ★ Competent Person of Inspector of Factories Government of Tamilnadu H1/ 2630 / 2018 Dt. : 16-05-2018
- ★ Govt. Regd. Approved Valuer F-19135
- ★ Govt. of India Regd. Valuer for Income Tax & Wealth Tax.
- ★ Panel Valuer Nationalised & Scheduled Bank



Residential & Industrial Buildings
Engineers & Valuers.,

103, 84-A, Sarojini Complex,
Senkadu, Kattoor Street,
Near by Women's Polytechnic College,
P.N. Palayam, Coimbatore - 641 037
E-mail : ramanicivil88@yahoo.com
reach3balu@gmail.com
Mobile : 98432 65083


- ★ Competent Person of Inspector of Factories and Boilers Government of Puducherry No. 239 / CIF & B / CP / A6 / 2019

DECLARATION

I, Er.M.BALASUBRAMANIAM, M.E., (Strul). Fiv., MIE., C.Engg. Balu Ramani Constructions, Residential & Industrial buildings Engineers & Valuers, 103, 84-A, Sarojini Complex, Senkadu, Kattor Street, Near by Womens Polytechnic College, P.N.Palayam, Coimbatore-641 037, do hereby declare that I possess the qualification and experience specified in the Table to rule 11 of the Madras Public Building (Licensing) Rules 1966 for issuing the certificate structural Soundness of the Building covered by the certificate.

- | | |
|---|---|
| 1. Name and Address of the Collectors Panel Engineer | Er.M.Balasubramaniam,M.E, (Strul) Fiv., MIE., C.Engg.
Balu Ramani Constructions, Residential & Industrial buildings Engineers & Valuers, 103, 84-A, Sarojini Complex, Senkadu, Kattor Street, Near by Womens Polytechnic College, P.N.Palayam, Coimbatore-641 037. |
| 2. Engineering Qualification | M.E (Strul) Fiv., MIE., C.Engg |
| 3. Coimbatore District Collector's Stability Panel Engineer | R.Dis.7194/2017/C2 |
| 4. Number of years of experience and nature thereof | A total of 25 years experience in Construction field (Designing and Execution of-Multistoried framed structures including 4 years service in Foreign Countries) |

Station : Coimbatore



Signature of the certifying Engineer
Er. M. Balasubramaniam, M.E. (Strul), MIE, FIV, C.Engg.,
STRUCTURE & SOIL STABILITY BANK VALUER
COLLECTOR'S PANEL ENGINEER CLASS-1A
LPA / SE / GR- II / 19/04/015
103, 84-A, Sarojini Complex,
Senkadu, Kattoor Street,
Near by Womens Polytechnic College,
P.N. Palayam Coimbatore - 641 037
Mobile No. 98432 65083

TO WHOMSOEVER IT MAY CONCERN

This is to certify that the Existing of approved M/s. Honey Bunch School, SF.No:38/A(P), Thoppampatti Village, Vellalapalayam Panchayat, Pollachi Taluk, Coimbatore Dist.

RAINWATER HARVESTING REPORT

This is to certify that the Existing of approved M/s. Honey Bunch School, SF.No:38/A(P), Thoppampatti Village, Vellalapalayam Panchayat, Pollachi Taluk, Coimbatore Dist.

- | | | | |
|----|----------------------------|----|---------------------------|
| 1. | Rain water harvesting pits | .. | 20 nos. |
| 2. | Pit size | .. | 300 mm dia and 1.00m deep |
| 3. | Capacity per pit | .. | 500 ltrs. |
| 4. | Total capacity | .. | 20x 500 = 10000 ltrs. |

WATER SUPPLY REPORT


This is to certify that the Existing of approved M/s. Honey Bunch School, SF.No:38/A(P), Thoppampatti Village, Vellalapalayam Panchayat, Pollachi Taluk, Coimbatore Dist.

- | | | | |
|----|--|------------------------------|-----------------------|
| 1. | Maximum no. of persons to be accommodated In the | .. | 1300 persons |
| 2. | Water requirement per person | .. | 45 litres / day |
| 3. | Max. water requirement for 1300 persons | | |
| 4. | Source for the above water requirement | | |
| | a. | From corporation water Inlet | .. 1500 litres / day |
| | b. | From Borewell - 1no | .. 14000 litres / day |

Place : Coimbatore

Date : 01.12.2020




M. BALASUBRAMANIAM, ME (Strs.), MIE, FIV, C.Engg
STRUCTURE & SOIL STABILITY BANK VALUER
COLLECTOR'S PANEL ENGINEER CLASS-1A
LPA / SE / GR-II / 19/04/015
103, 84-A, Sarujini Complex,
Senkadu, Kattoor Street,
Near by Womens Polytechnic College,
P.N. Palayam, Coimbatore - 641 037.
Mobile No: 98432 65083

Residential & Industrial Buildings
Engineers & Valuers.,

- ★ Chartered Engineer ---- 147273-3
- ★ Constructions & Consulting Civil Engineer
- ★ Govt. Approved Coimbatore District Collector's Soil Stability Panel Engineer
R.Dis : 7194 / 2017 / C2 - CLASS - 1A
- ★ Licensed Bldg. Surveyor
for Coimbatore Corporation
Reg. No. 246 / 2009 / Grade I.
- ★ Competent Person of
Inspector of Factories
Government of Tamilnadu
H1/ 2630 / 2018 Dt. : 16-05-2018
- ★ Govt. Regd. Approved Valuer F-19135
- ★ Govt. of India Regd. Valuer for Income Tax & Wealth Tax.
- ★ Panel Valuer Nationalised & Scheduled Bank




103, 84-A, Sarojini Complex,
Senkadu, Kattoor Street,
Near by Women's Polytechnic College,
P.N. Palayam, Coimbatore - 641 037
E-mail : ramanivil88@yahoo.com
reach3balu@gmail.com
Mobile : 98432 65083

- ★ Competent Person of
Inspector of Factories and Boilers
Government of Puducherry
No. 239 / CIF & B / CP / A6 / 2019

STABILITY CERTIFICATE
FORM - A

- | | | | |
|----|--|----|---|
| 1. | Name of the Institution | .. | M/s. Honey Bunch School. |
| 2. | Location (Street Number, Ward Number Name of Place, ie. Corporation, Municipality / Panchayat Union /Township/Cantonment | .. | SF.No:38/A(P),
Thoppampatti Village,
Vellalalayam Panchayat,
Pollachi Taluk,
Coimbatore Dist. |
| 3. | By Whom Managed | .. | Meenakshi Educational
Activity Trust. |
| 4. | Details of the building in the campus: | .. | School Building. |
| 5. | Condition of the building | .. | Good |
| | Year of Construction | .. | 2013,2017,2019. |
| | Ground,First,Second Floor | .. | |
| 6. | Authority who have approved the Construction from structural point of view | .. | Nil. |



B. V. ...2
M. BALASUBRAMANIAM, M.E. (Strs), MIE, FIV, C.Engg.,
STRUCTURE & SOIL STABILITY BANK VALUER
COLLECTOR'S PANEL ENGINEER CLASS-1A
LPA / SE / GR-II / 19/04/015
103, 84-A, Sarojini Complex,
Senkadu, Kattoor Street,
Near by Womens Polytechnic College,
P.N. Palayam, Coimbatore - 641 037.
Mobile No: 98432 65083

7. Details of construction of the building (particulars of the foundation soil, specification of the various parts under)
- | | | | |
|----|--|----|--------------------------------|
| 1. | Foundation | .. | Stone Masonry in Cement Mortar |
| 2. | Basement | .. | Stone Masonry in cement mortar |
| 3. | Super Structure | .. | Brick Work in cement mortar |
| 4. | Floor and roof
Ground, First, Second Floor. | .. | RCC Roof. |
8. Any partition walls intermediate Floor which do not have proper support .. Nil
9. Verandah pillars:
- | | | | |
|----|----------------------|----|--------|
| a. | Structural Soundness | .. | Sound. |
| b. | Present condition | .. | Good |
10. Beams, joints etc & Rafters
- | | | | |
|----|----------------------|----|--------|
| a. | Structural soundness | .. | Sound. |
| b. | Present condition | .. | Good |
11. Roof:
- | | | | |
|----|----------------------|----|-------|
| a. | Structural soundness | .. | Sound |
| b. | Present condition | .. | Good. |
12. i Miscellaneous items
- | | | | |
|----|------------------------------------|----|-----------|
| a. | Stair case | .. | Provided. |
| b. | Present condition & width of stair | .. | Good |
| c. | Structural soundness | .. | Sound. |
- ii. Balconies
- | | | | |
|----|-------------------------|----|-------|
| a. | Are they adequate width | .. | Good |
| b. | Structural soundness | .. | Sound |
| c. | Present condition | .. | Good |



6.11.2013
BALASUBRAMANIAM, ME (Strs), MIE, FIV, C.Engg.,
 STRUCTURE & SOIL STABILITY BANK VALUER
 COLLECTOR'S PANEL ENGINEER CLASS-1A
 LPA / SE / GR-II / 19/04/015
 103, 84-A, Sarojini Complex,
 Senkadu, Kattoor Street,
 Near by Womens Polytechnic College
 P.N. Palayam, Coimbatore - 641
 Mobile No: 98432 65023

- iii. **Electrical installation:**
- a. Present condition .. Good
- b. Concealed wiring or open wiring .. Concealed wiring
13. **Fire protection**
- The suitable provisions made by way of fire fighting appliances .. Provided.
14. If they are adequate in regard to entrance to exist for the emergencies .. Yes
15. General remarks .. Good.
16. App Cost Building .. 3.0C
17. **Total Building Area.**
- Ground Floor : 17,041 Sq ft.
- First Floor : 16,395 Sq ft.
- Second Floor : 16,395 Sq ft.

Date : 01.12.2020

Place : Coimbatore.



B. Balasubramaniam
 M. BALASUBRAMANIAM, ME(Strs), MIE, FRC, Engg.
 STRUCTURE & SOIL STABILITY BANK VALUER
 COLLECTOR'S PANEL ENGINEER CLASS-1A
 LPA / SE / GR-II / 19/04/015
 103, 84-A, Sarojini Complex,
 Senkadu, Kattoor Street,
 Near by Womens Polytechnic College
 P.N. Palayam, Coimbatore - 641 014
 Mobile No: 98432 65023

FORM - B

(Form of Certificate of structural soundness under sub-section (4) of Section 4 of the
Tamilnadu Public Buildings (Licensing) Act, 1965
(Tamilnadu Act, 13 of 1965) referred to in rule 4 of the Tamilnadu Public buildings
(Licensing) Rules 1966)

Place : Coimbatore
Date : 01.12.2020

Signature of the Engineer



STATEMENT TO ACCOMPANY THE CERTIFICATE OF
STRUCTURAL SOUNDNESS

- | | | | |
|----|--|----|---|
| 1. | Location of the building door
Number Street and name of the Place | .. | SF.No:38/A(P), Pollachi Taluk,
Thoppampatti Village,
Vellalpalayam Panchayat,
Coimbatore Dist. |
| 2. | Age of the building | .. | 7,3,1, Yrs above. |
| 3. | Purpose for which the building will be
structurally sound | .. | School Building. |
| 4. | The period for which the building will
be structurally sound: | .. | 3 years(2020 to 2023)
(01.12.2020 to 30.11.2023) |
| 5. | Number of persons to be accommodated | .. | 1300 Students+ Staff
Non Teaching Staff, |
| 6. | Remarks | .. | Nil |

Place : Coimbatore
Date : 01.12.2020

Signature of the Engineer



M. Balasubramanian
M. BALASUBRAMANIAM, ME (Strs), MIE, CIV, Engg.
STRUCTURE & SOIL STABILITY BANK VALUER
COLLECTOR'S PANEL ENGINEER CLASS-1A
LPA / SE / GR-II / 19/04/015
103, 84-A, Sarojini Complex,
Senkudu, Kartoor Street,
Near by Womens Polytechnic College.
P.N. Palayam, Coimbatore - 641 037
Mobile No: 98432 65083

FORM -C

(Form of Certificate of structural soundness under sub-section (4) of Section 4 of the Tamilnadu Public Buildings (Licensing) Act, 1965 (Tamilnadu Act, 13 of 1965) referred to in rule 4 of the Tamilnadu Public Buildings (Licensing) Rules, 1966)

1. Foundation Depth

Below ground level	..	2.5 m
Nature of soil met with at foundation level	..	Hard Gravel with rock.
Probable safe bearing capacity of the statement with at foundation	..	200 KN/m ² .
Pressure at foundation	..	300 KN/m ² .

2. Superstructure

Maximum stress in the most critical section of masonry and concrete	..	RCC column footing 1:1.5:3 - 370 KN/sqm
Nature of masonry and concrete and its safe permissible stresses	..	Brick in CM 60 KN/sqm RCC M20 mix -5N/sqmm

I have satisfied that the buildings are structurally sound to be used as public buildings for the purpose specified in the statement.

The structural soundness of the buildings has been verified taking in account ISI loading standard 875 latest version and other relevant Indian standard code of practice and I declare the building are structurally sound to be used as a public building for the purpose noted in the statement.

It is certified that the **M/s. Honey Bunch School Building** to be constructed has been designed for the above mentioned loads and seismic loads as per relevant codes specified by Bureau of Indian Standards 3 years - 2020- 2023 (01.12.2020 to 30.11.2023)

Place: Coimbatore

Date : 01.12.2020



Signature of the Engineer.

B. V. Subramaniam
M. BALASUBRAMANIAM, ME (Strl., MIE, FIVC, Engg.,
STRUCTURE & SOIL STABILITY BANK VALUER
COLLECTOR'S PANEL ENGINEER CLASS-1A
LPA / SE / GR-II / 19/04/015
103, 84-A, Sarojini Complex,
Senkadu, Kattoor Street,
Near by Womens Polytechnic College,
P.N. Palayam, Coimbatore - 641 037
Mobile No: 98432 65083

Proceedings of the District Collector, Coimbatore.
Present : Thiru.T.N.Hariharan, I.A.S.,

Ref.No.7194/2017/C2

Dated: 01.09.2017.

Sub : Tamil Nadu Public Building Licensing act 1965 - Upgradation of the name of Thiru.M.Balasubramaniam in the panel of private practicing engineers from CLASS I to CLASS IA category in Coimbatore district - approval of the board of engineers - orders issued -reg

Ref : 1. Superintending Engineer, PWD Buildings(C&M), Coimbatore
Lr.No.DB/DO2/F1142/119M/2017 dated.25.05.2017.
2. Engineer-In-Chief (Buildings),Chief Engineer(Buildings)
Chennai Region and Chief Engineer(General), PWD, Chennai
Lr.no.AEE/T1/AE/21124/2017 dated: 11.08.2017.

ORDER-

The Engineer-In-Chief (Buildings),Chief Engineer(Buildings) Chennai Region and Chief Engineer(General), PWD, Chennai in the reference 2nd cited has stated that the Board of Engineering Meeting resolved and approved the name of Thiru.M.Balasubramaniam (D.O.B.-06.05.1971) for inclusion and registering in the panel of Private Practicing Engineer from CLASS I to CLASS IA category (Buildings, the cost of which exceeds Rs.50 lakhs as per G.O.Ms.No.43, Municipal Administration & Water Supply (MA4) Department, dated.17.02.2011) in Coimbatore District.

Accordingly, the Thiru.M.Balasubramaniam has been included in the panel of Private Practicing Engineer from CLASS I to CLASS IA category (Buildings, the cost of which exceeds Rs.50 lakhs) in Coimbatore district and entered the name against Sl.no. 05/2017 in the register of panel of Private Practicing Engineer maintained in this office.

Sd/-T.N.Hariharan
District Collector,
Coimbatore.

To

✓ Thiru.M.Balasubramaniam,
103, 84A, Sarojini Complex,
Sengodu Kattur Street, P.N. Palayam,Coimbatore-641037

Copy to

1. Superintending Engineer, PWD Buildings(C&M), Coimbatore
2. Engineer-In-Chief (Buildings),Chief Engineer(Buildings) Chennai Region and Chief Engineer(General), PWD, Chepauk, Chennai

/True Copy/

For District Collector

01/09/17

FORM -D

(Form of License under sub-section (1) of section 6 of the Tamil Nadu public building (licensing act of 1965 (TamilNadu act 13 of 1965) referred to in rule 6 of the Tamil Nadu public building (licensing) Rule 1965.

License No. 26/2020/A1

Date : 20.11.2020

K dis No:4836/2020/A1

License fee Rs.1000/-
(Rupees One Thousand only)

License is hereby granted to The Principal, Honey Bunch School, Thoppampatti Village, Vellalapalayam Panchayat, Pollachi, Pollachi Taluk, Coimbatore District for the purpose and in respect of the building specified in the statement below and subject to the condition and for the period hereunder

The period of validity of the license shall be valid from 01.12.2020 to 30.11.2023.

THE STATEMENT TO ACCOMPANY LICENCE

Location of the building	Purpose of which the building is to be used	No of person to be accommodated
The Principal, Honey Bunch School, S.F.No.38/A(P), Thoppampatti Village, Vellalapalayam Panchayat, Pollachi Taluk, Coimbatore District.	Running School	1300 No's



[Signature]
20/11/2020
TAHSILDAR,
POLLACHI.

To

The Principal,
Honey Bunch School,
S.F.No.38/A(P),
Thoppampatti Village,
Vellalapalayam Panchayat,
Pollachi Taluk,
Coimbatore District.

[Signature]
20.11.2020